

## DRAFT

- Insufficient parking
- Inaccessible, uninviting split-level side entrance
- Lack of space for quiet and louder uses to coexist
- Outdated, cramped public and staff space in Youth Services
- Elevator modernization
- Community meeting room overbooked, in need of technological updates, and capacity to be re-configured to accommodate both large and small groups
- Inadequate and inefficient HVAC system.
- Shelving inaccessible to many patrons, crowded, and blocks natural light
- Lighting substandard and inefficient
- No dedicated tech help/maker spaces
- Lack of dedicated spaces for pre-literacy programs
- Lack of dedicated spaces for teens and tweens
- Main sewer line failure/backup
- Bathrooms unsafe and inadequate
- Safety/Security challenge of a four-story building with three entrances
- Lack of space for non-book collections
- Lack of outdoor space/options for programming
- Icy/treacherous main steps in winter
- Heavy/awkward front door difficult to open/access
- Limited storage areas often serving dual purposes (book drop/storage, pump room/storage, youth office/storage)