

ILSLEY PUBLIC LIBRARY – FACILITIES PRIORITIZATION


This PDF presents the raw results of a survey of the 5 members of the Board of Trustee of Ilsley Public Library plus the Library Director. The survey followed a discussion at a board meeting on September 14, 2020 at which the needs of the library facility were discussed. Members completed the survey between September 14 and September 18, 2020.

The results of this survey are in no way binding, this was simple a fairly crude instrument to determine the views of the current board on the priorities to be pursued in a library renovation/expansion project.

The scale is from 1 to 5 with 1 being most important or essential and 5 being a lower priority or perhaps a feature that the library could do without. Items rated 1 or 2, on the left of the scale as presented, are considered to be of greater priority than items rated 4 or 5 on the right side of the scale.


Create four, distinct, age-appropriate, dedicated spaces for preschoolers, young children, tweens, and teens

6 responses




Ensure that childrens' spaces are above the basement level

6 responses




Ensure that childrens' spaces have natural light

6 responses



Ensure that childrens' spaces have unobstructed lines of sight.


6 responses



ACCESSIBILITY


Entrances are welcoming and accessible to all (including those in wheelchairs) and permit reaching main floor (i.e. circulation desk) without use of elevator

6 responses




There is a grade level entrance at Main Street

6 responses




There is a grade level entrance at the rear parking area

6 responses




Replace existing shelving in children's area and adult stacks with shelving that is within easy reach of all users

6 responses




Install an ADA-approved elevator

6 responses




The elevator should be centrally located

6 responses



The elevator should be in sight of the circulation desk


6 responses



HEATING/COOLING/LIGHTING/WIRING/ MOISTURE ABATEMENT


Install an HVAC system that is reliable, cools and heats the building evenly, is efficient and environmentally benign

6 responses




The HVAC system should include a building-wide mechanical ventilating system

6 responses




Replace or repair existing windows that leak or do not open

6 responses




Upgrade existing light fixtures with ones that provide better light and are efficient and reliable

6 responses




Update and expand electrical and technological wiring throughout the building

6 responses



Prevent water from seeping through the foundation into the basement and existing community room


6 responses



BATHROOMS


Create safe, modern, public bathrooms

6 responses




Create 5 such bathrooms – at least one on each floor

6 responses



Be sure each bathroom can serve more than one individual at a time


6 responses



SPACE


Create a building that is flexible enough to accommodate evolving programmatic developments

6 responses




Move MCTV out of the fourth floor so that it no longer violates state egress codes

6 responses




Convert current MCTV space into a meeting room

6 responses




Create a technology classroom or teaching computer / digital media lab

6 responses




Enhance space for public computers

6 responses




Create an additional three meeting rooms for 5-10 persons

6 responses




Create more storage space

6 responses




Create additional work space for staff

6 responses




Create effective signage

6 responses




Create a new staff kitchen

6 responses




Create an assortment of small, semi-private spaces where one or two patrons can read quietly

6 responses



Renovate the original 1924 building


6 responses



COMMUNITY MEETING ROOM


Build a larger community meeting room

6 responses




The community meeting room should be free of moisture problems

6 responses




The community meeting room should have a ceiling high enough to allow images to be projected without being cropped and able to be seen from all seats

6 responses



The community meeting room should be fully wired for technology

6 responses



The community meeting room should be easily subdivided into three or more smaller spaces.

6 responses

